



Preliminary Information

PIT5849A Tail Lights Remain On After Passive Locking and/or Dead Battery

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500HD/3500HD	2022	All	All	All	All
GMC	Sierra 2500HD/3500HD	2022	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that the rear tail / parking lights stay on and do not time out after exiting the vehicle and passive locking the vehicle. This condition can lead to a dead battery.
Cause	The cause of this condition is a BCM Software issue.

Correction:

GM Engineering is working on a fix. Because this condition only occurs if passive locking is used please turn off passive locking in vehicle settings until a fix is released.

Additional SI Keywords

Park left right lamps lamp lighting light taillight taillamp

Version History

Version	2
Modified	07/26/2021 - Created on. 09/23/2021 - Updated to remove the light duty trucks.



GENERAL MOTORS